

# Common spare parts “Equipment”

2013-01-02

## Cold paint equipment

### *BM C 220 / 440*

- Pressure regulator (500608)
- Manometer 0-10 bar (500518)
- Manometer on tank 0-10 bar (503521)
- Relief valve 8.5 bar (503130)
- Shaft seal kit for agitator (504682)
- Bearings for agitator shaft (2 pieces needed) (500638)
- Bush bearing for agitator (500645)
- Gasket for lid (101830)



# Common spare parts “Equipment”

2013-01-02

- Check valve for air connection

(500936)



- Ball valve for air ( 1/2” – 3 way )

(503184)



- Ball valve for paint. ( 1” – 2 way )

(500950)



- Hydraulic motor for agitator

(511374)



- O-ring for agitator

(504469)



- Paint filter

(106596)



- Gasket for paint filter

(111715)



- Copper ring for nut. (paint filter)

(504974)



# Common spare parts “Equipment”

2013-01-02

## Paint gun BM C 6 (Pressure tank)

➤ Gasket set for gun. (506351)



• Needle for paint (108943)



• Paint shutter (108220)



• Split pin (504416)



➤ Paint nozzles. Also see nozzle list

○ ø 2,5 mm (Premark system) (103754)



○ ø 6,0 mm (model A) Borum Standard (108850)



○ ø 8,0 mm (model A) (108215)



# Common spare parts “Equipment”

2013-01-02

➤ Air atomizer nozzles. Also see nozzle list

- ø 2,5 mm (Premark system) (110203)
- ø 6,0 mm (model A) Borum Standard (108844)
- ø 8,0 mm (model A) (108343)
- Nozzle set complete ø 6,0 mm Borum standard (504468)
- Limitation sleeves (2 pieces. needed) (100255)
- 8 mm plastic hose for gun. (1 meter) (503819)
- 10 mm plastic hose for gun. (1 meter) (503820)

