

# Congratulation on your new BM Pre-Heater

2015-18-11

## BM Pre-Heater

You have now received your new Pre-Heater from Borum.

To ensure the reliability, service and maintenance is very important.

### Parts for first 50 hours service

Boiler

- Fuel filter 1 pc. to each oil burner (only if mounted) (500413)

(It is important to have the first service check very early, because when starting up the circuit is cleaning it self and all the impurities can cause clogging of the filter with the risk of too low lubrication and flow)

The next service must be 1000 hours / 6 month

### Parts for every 1000 hours / 6 month

Boiler

- Fuel filter 1 pc. to each oil burner (only if mounted) (500413)

### We recommend doing the following minimum each year:

To change heat oil (Only ID Pre-Heaters), and make service on the oil burner (See details in the manuals)

- Heat oil Litres depending of size (only on ID boilers) (500383) Q8 GLUCK H or similar
- Nozzle 1 pc for oil burner (only if mounted)

Size of nozzle is depending of boiler type see manual for burner

Borum Industri A/S, Højvangsvej 10,  
Hadbjerg, DK-8370 Hadsten, Denmark, CVR nr. DK 19085694  
Tel: + 45 87 613 213, Fax: + 45 87 613 214,  
www.borum.as • e-mail: info@borum.as



– it's straightforward

**Congratulation on your new BM Pre-Heater**

2015-18-11

**PARTS FOR THE FIRST 50 HOURS SERVICE  
IS INCLUDED IN THIS PACKAGE**

Borum Industri A/S, Højvangsvej 10,  
Hadbjerg, DK-8370 Hadsten, Denmark, CVR nr. DK 19085694  
Tel: + 45 87 613 213, Fax: + 45 87 613 214,  
[www.borum.as](http://www.borum.as) • e-mail: [info@borum.as](mailto:info@borum.as)



– it's straightforward